



LEGEND			
<b>DRAINAGE</b>	<b>FENCES</b>	<b>LEVELS</b>	<b>SERVICES</b>
cc cover	ba barrier	C.L. Cover Level	bs bus shelter
dc drainage channel	bw barbed wire	F.L. Floor Level	bt British Telecom
fd foul drain	cb closeboard	I.L. Invert Level	cair cable to
gv gully	ci corrugated iron	OSM Ordnance Survey	ep electricity pole
ks kerb outlet	cl chainlink	F.L. Bench Mark	fh fire hydrant
M.H. manhole	cp concrete post	T.L. Threshold Level	kl keep left bollard
rw roading pipe	gt gate	W.L. Water Level	lp lamp post
ppp rainwater pipe	ll larch lap		oc overhead cable
sd storm drain	mp metal post		pk phone kiosk
svp soil vent pipe	mr metal rail		sv stop valve
	ps post		slap sign
	pr post & rail		ts tactile slabs
	pw post & wire		we wood edging
	sw stone wall		sf flush setts
	tw top of wall		st raised setts



Revision A: July 2019  
 Ditch to West of Oakley Farm and  
 field to South of Farmyard surveys.

NOTE:  
 All drainage pipe sizes have been measured from the  
 surface. Chamber access has not been gained for  
 safety reasons, therefore sites should be regarded  
 as approximate.

**RUXTON**  
 SURVEYS

The Long Barn  
 Mitre Farm  
 Corpe Lawn  
 Gloucestershire  
 Tel. 01684 217217  
 Mob. 07831 861822  
 www.ruxtonsurveys.co.uk  
 enquiry@ruxtonsurveys.com

LOCATION:  
**LAND AT OAKLEY  
 CHELTENHAM  
 GLOUCESTERSHIRE**

CLIENT:  
**ROBERT HITCHINS LTD**

**SITE SURVEY  
 (SHEET 2 OF 3)**

SCALE: 1 to 500  
 DATE: NOVEMBER 2018  
 SHEET SIZE: A0

DRAWING NUMBER: 18169/02A  
 DRAWN BY: S.P.T.

396650 E  
 396700 E  
 396750 E  
 396800 E  
 396850 E  
 396900 E  
 396950 E  
 397000 E

222100 N  
 222150 N  
 222200 N  
 222250 N  
 222300 N  
 222350 N  
 222400 N  
 222450 N  
 222500 N  
 222550 N  
 222600 N